



Shafter Community Enforcement Update

Second Quarter 2026

Covering enforcement activities in the community from 4/1/2026 through 6/30/2026:

Stationary Source Inspections

- 19 total stationary source inspections conducted
- 1 source test observation

Enforcement Action Summary

- Stationary Source (Facility): 5 violation notices issued (1 procedural/administrative, 4 emissions related)
- Non-stationary Source (Non-facility): 0 violation notices issued

Public Complaints

- 2 total public complaints responded to in the community
 - 1 fugitive dust
 - 1 other
- 0 violation notices issued
- Complaints can be reported to the District by:
 - Telephone: (800) 870-1037
 - District website: www.valleyair.org
 - Through the District mobile app (Valley Air app)

Learn more: community.valleyair.org

Summary of Violations

Date	Type	Violation #	Issued To	Facility ID	Location	Description	Rules
4/6/2026	NOV	5037187	Dj's Food Mart	S-2813	31110 7Th Standard Rd, Bakersfield	Failure to conduct and pass required vapor recovery source testing within 30 days of anniversary date.	4621 (Gasoline Transfer into Stationary Storage Containers, Delivery Vessels, and Bulk Plants), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
4/10/2026	NOV	5037206	South Valley Almond Co LLC	S-3152	15443 Beech Ave, Wasco	Failure to maintain the yearly emissions of phosphine below permitted limit of 161.5 lb/yr.	2070 (Standards for Granting Applications), 4102 (Nuisance)
4/23/2026	NOV	55959	Dj's Food Mart	S-2813	31110 7Th Standard Rd, Bakersfield	Failure to maintain vapor recovery system. Torn whip hose on fueling point #8.	2070 (Standards for Granting Applications), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
5/6/2026	NOV	5037337	LKMP Properties	S-9202	31109 7Th Standard Rd, Shafter	Failure to maintain the vapor recovery system. (Ball valve "A" closed on Clean Air Separator)	2070 (Standards for Granting Applications), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
5/13/2026	NOV	55961	Minter Field Airport District	S-1736	201 Aviation Street, Shafter	Failure to maintain the vapor recovery system. 1. Torn upper hose 2. Excess liquid >100 (500mL)	2070 (Standards for Granting Applications), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)