



## **Shafter Community Enforcement Update**

### **Third Quarter 2023**

Covering enforcement activities in the community from 7/1/2023 through 9/30/2023:

#### **Residential Wood Burning – District Rule 4901**

- District restrictions in effect from Nov. 1 – Feb. 28/29 each year
- CERP commitment: Enhanced enforcement (four hours of enforcement on each wood burning curtailment day)

#### **Illegal Open Burning – District Rule 4103**

- CERP commitment: One targeted enforcement effort every quarter
- 2 public complaints received
- 1 violation notice issued

#### **Statewide Anti-Idling Enforcement**

- CERP commitment: One targeted enforcement effort every quarter
- No violations of CARB's truck and bus regulation observed

#### **Stationary Source Inspections**

- CERP commitment: Increased inspection frequency at facilities with emission violations in the last 3 years
- 27 total stationary source inspections
- 7 violation notices issued (2 procedural/administrative, 5 emissions related)

#### **Public Complaints**

- 2 total public complaints responded to in the community
  - 2 open burn
- No violation notices issued
- Complaints can be reported to the District by:
  - Telephone: (800) 870-1037
  - District website: [www.valleyair.org](http://www.valleyair.org)
  - Through the District mobile app (Valley Air)

**Learn more: [community.valleyair.org](http://community.valleyair.org)**

Date/Fecha	Type/Tipo	Violation #	Issued To	Facility ID	Location	Description
7/3/2023	NOV	5031285	South Valley Almond Co Llc	S-3152	15443 Beech Ave, Wasco	This commodity processing and storage fumigation operation shall not exceed 282 lbs emissions of phosphine in any consecutive 365 day period.
7/7/2023	NOV	5031257	J.P. Oil Company, Llc.	S-8561	Rio Bravo Gas Plant, (Section 27, T28S, R25E), Shafter	Discovery of (2) greater than 50,000 ppm leaks
7/7/2023	NOV	5031293	J.P. Oil Company, Llc	S-2865	Light Oil Central, Shafter	Discovery of an Open Ended Line Rule 4409: (1) leak greater than 50k ppm on Well # Osborn 1-3 Rule 4623: (1 leaks) on tank #11 (PTO-39); (2 leaks) on Tank # 8 (PTO-52) Rule 4702: Exceeding the CO limits on Engine Kernco32 (PTO-73) Rule 4624: Exceeding leak greater than 1,000 ppm on hose (PTO-68)
8/2/2023	NOV	5031419	Shafter Wasco Gin	132182	1/4 mi N Jack Ave & 1/5 mi E Shafter Ave, Shafter	Burning more material than authorized Burning at location not listed on burn permit Unattended burn
8/15/2023	NOV	5031469	Harbor Pilot Inc		16030 Driver Rd, Shafter	Operating a wood coating operation without District permit
8/15/2023	NOV	5031338	Jack A Fierstadt	S-9051	16000 Driver Road, Bakersfield	Operating on suspended permits
9/5/2023	NOV	55257	Corner Market #2	S-9170	6000 E Lerdo Hwy, Bakersfield	Failure to maintain vapor recovery system (500ml excess liquid from fueling point #8)
9/13/2023	NOV	5031555	California Resources Production Corp	S-1737	Light Oil Central, Kern County	Discovery of 3 (three) gas leaks greater than 50,000 ppm.