



Stockton Enforcement Update

Fourth Quarter 2023

Covering enforcement activities in the community from 10/1/23 through 12/31/23:

Fugitive Dust – District Regulation VIII

- CERP Commitment: One targeted enforcement effort during the 2nd and 3rd quarters, which tend to be the driest times of the year and most likely to have issues with fugitive dust from earthmoving activities
- No fugitive dust complaints received

Statewide Anti-Idling Enforcement

- CERP Commitment: One targeted enforcement effort during each quarter.
- No public complaints of idling diesel trucks received
- No violations of CARB's anti-idling regulation observed during District enforcement

Stationary Source Inspections

- CERP commitment: Increased inspection frequency at facilities which receive an emissions violation
- 37 total stationary source inspections
(33 compliance inspections & 4 source test observations)

Enforcement Action Summary

- Stationary Source: 13 violation notices issued (8 procedural/administrative, 5 emissions related)
- Non-stationary Source: 4 violation notices issued

Public Complaints

- 6 public complaints responded to in the community
(4 open burn, 1 asbestos, 1 odor)
- Complaints can be reported to the District by:
 - Telephone: (800) 870-1037
 - The District website: www.valleyair.org
 - Through the District mobile app (Valley Air app)

Learn more: community.valleyair.org

Date	Type	Violation #	Issued To	Facility ID	Location	City	Description	Rules
10/3/2023	NOV	5031662	Ganesha Investments, Inc.		1801 E Market St	Stockton	Failure to comply with NESHAP 40 CFR Part 61.145. 1)No trained personnel on site, 2) Regulated Asbestos Containing Materials not maintained wet, 3) Failure to contain in a leak-tight container 4) Visible Emissions 5) Improper disposal, 6) Failure to Notify, 7) Failure to pay fees, 8) Failure to thoroughly survey for asbestos.	4002 (National Emission Standards for Hazardous Air Pollutants)
10/3/2023	NOV	5031663	MTS Engineering		1801 E Market St	Stockton	Failure to comply with NESHAP 40 CFR Part 61.145. 1)No trained personnel on site, 2) Regulated Asbestos Containing Materials not maintained wet, 3) Failure to contain in a leak-tight container 4) Visible Emissions 5) Improper disposal, 6) Failure to Notify, 7) Failure to pay fees, 8) Failure to thoroughly survey for asbestos.	4002 (National Emission Standards for Hazardous Air Pollutants)
10/11/2023	NOV	49072	Calamco Cogen Llc	N-7082	2323 Port Road G	Stockton	1) Failure to maintain NOx emissions below permit limits. 2) Failure to notify District of NOx exceedance.	2070 (Standards for Granting Applications) 2201 (New and Modified Stationary Source Review Rule) 4702 (Internal Combustion Engines - Phase 2)
10/11/2023	NOV	5031701	Nustar Terminals Ops Partnership Lp	N-829	2941 Navy Drive	Stockton	During a source test conducted on 6/21/23, the facility exceeded the VOC emissions limit of 0.015 pounds per thousand gallons of gasoline loaded.	2070 (Standards for Granting Applications) 2201 (New and Modified Stationary Source Review Rule) 2520 (Federally Mandated Operating Permits)
10/18/2023	NTC	5031801	Best Express Foods Inc	N-298	2651 S Airport Way	Stockton	Failure to obtain an Authority to Construct prior to installing and operating equipment - Permit Exemption Determination application required.	2010 (Permits Required)
10/26/2023	NTC	5031714	LMG STOCKTON, INC DBA THE RECORD	N-819	612 E Market St	Stockton	Failure to submit the 2022 emissions report to the San Joaquin Valley APCD by May 1st, 2023.	93403 (CA Code of Regulations, Title 17)
10/26/2023	NTC	5031750	LKQ	N-7811	2041 Navy Dr	Stockton	Failure to submit the 2022 emissions report to the San Joaquin Valley APCD by May 1st, 2023.	93403 (CA Code of Regulations, Title 17)
10/26/2023	NTC	5031758	ELEANOR SADE	N-8830	2800 S El Dorado St	Stockton	Failure to submit the 2022 emissions report to the San Joaquin Valley APCD by May 1st, 2023.	93403 (CA Code of Regulations, Title 17)
10/31/2023	RCAT	5031809	M&L Commodities, Inc	N-7489	2323 Port Road A	Stockton	Failure to maintain recordkeeping per permit condition #15.	4702 (Internal Combustion Engines - Phase 2)
11/7/2023	NOV	53678	Cal State Univ C/O Grupe Huber Company	N-818	805 Magnolia St	Stockton	Failure to maintain Phase II vapor recovery system (Torn whipnose). 1. Failure to maintain NOx below limits (12 ppm at 3% O2) - Condition 5. 2. Failure to have units tuned at least twice each calendar year, from four to eight months apart - Condition 7	2070 (Standards for Granting Applications) 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
11/7/2023	NOV	5031829	Judicial Council Of California	N-9129	180 E Weber Ave	Stockton		2070 (Standards for Granting Applications) 4307 (Boilers, Steam Generators, and Process Heaters - 2.0 to 5.0 MMBtu/hr)
11/20/2023	NOV	5031877	DTE Stockton, Llc	N-645	2526 W Washington St	Stockton	Failure to provide the wet scrubber with monitoring equipment that continuously monitors and records the effluent pH and flow rate of the scrubber liquid	2070 (Standards for Granting Applications) 2201 (New and Modified Stationary Source Review Rule) 2520 (Federally Mandated Operating Permits)
11/28/2023	NOV	5031961	City of Stockton	N-805	1465 S Lincoln St	Stockton	Failure to conduct and pass the required vapor recovery performance testing.	2010 (Permits Required)
11/29/2023	NOV	5031987	Jose Zavala		1894 Lucerne Ave	Stockton	Use of a wood burning fireplace, wood burning heater, or outdoor wood burning device on an episodic wood burning curtailment day.	4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
12/5/2023	NOV	5032039	Sandra Galindo-Mujica		770 Howard St	Stockton	Use of a wood burning fireplace, wood burning heater, or outdoor wood burning device on an episodic wood burning curtailment day.	4901 (Wood Burning Fireplaces and Wood Burning Heaters)
12/12/2023	NOV	53685	Mobil Stockton #1/Abdo Nashir	N-175	642 N Hunter St	Stockton	Failure to maintain the Phase II vapor recovery system (Fueling Point #7 & 11 have torn whipnose; Nozzle #5 torn nozzle boot). Tagged out Dispenser # 5, 7 and 11.	2070 (Standards for Granting Applications) 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
12/18/2023	NTC	28571	Delta Charter	N-4283	440 W Dr. Martin Luther King Jr Blvd	Stockton	Operating without a valid permit to operate; failure to submit a transfer of ownership application.	2010 (Permits Required)