



Shafter Community Enforcement Update

Second Quarter 2024

Covering enforcement activities in the community from 4/1/2024 through 6/30/2024:

Residential Wood Burning – District Rule 4901

- District requirements in effect from Nov. 1 – Feb. 28/29 each year
- CERP commitment: Enhanced enforcement (four hours of enforcement on each wood burning curtailment day)
- No public complaints received
- No violation notices issued

Illegal Open Burning – District Rule 4103

- CERP commitment: One targeted enforcement effort every quarter
- 1 public complaint received
- No violation notices issued

Statewide Anti-Idling Enforcement

- CERP commitment: One targeted enforcement effort every quarter
- No violations of CARB's truck and bus regulation observed

Stationary Source Inspections

- CERP commitment: Increased inspection frequency at facilities with emission violations in the last 3 years
- 19 total stationary source inspections (18 compliance inspections, 1 source test observation)

Enforcement Action Summary

- Stationary Source: 6 violation notices issued (4 emissions related, 2 procedural/administrative)
- Non-stationary Source: 1 violation notice issued (procedural/administrative)

Public Complaints

- 3 total public complaints responded to in the community (1 open burn, 2 other)
- Complaints can be reported to the District by:
 - Telephone: (800) 870-1037
 - District website: www.valleyair.org
 - Through the District mobile app (Valley Air app)

Learn more: community.valleyair.org

Summary of Violations

Date	Type	Violation #	Issued To	Facility ID	Location	Description	Rules
5/10/2024	NOV	5033043	California Resources Production Corp	S-1737	900 Old River Rd, Bakersfield	One (1) gas leak greater than 50,000 ppm.	95669 (CA Code of Regulations, Title 17)
6/3/2024	NTC	5031972	Jaco Hill	S-2369	105 E Lerdo Hwy, Shafter	Failure to conduct and pass the required vapor recovery performance tests (CAS, dispenser integrity, and V/L). Tests were not conducted by a certified technician.	2070 (Standards for Granting Applications) 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
6/12/2024	NOV	5033159	Plains Lpg Services Lp	S-71	7Th Standard Rd & Beech Ave, Shafter	A leak exceeding 50,000 ppm was discovered on the crankcase vent of compressor C-61.	2070 (Standards for Granting Applications) 2520 (Federally Mandated Operating Permits) 4624 (Transfer of Organic Liquids)
6/12/2024	NOV	5033160	Plains Lpg Services Lp	S-71	7Th Standard Rd & Beech Ave, Shafter	20,000 ppm leak discovered on a flex line arm.	2070 (Standards for Granting Applications) 2520 (Federally Mandated Operating Permits) 4624 (Transfer of Organic Liquids)
6/12/2024	NOV	5033163	Minter Field Airport District	S-1736	Minter Field, Shafter	FAILURE TO CONDUCT AND PASS REQUIRED VAPOR RECOVERY PERFORMANCE TESTING	4621 (Gasoline Transfer into Stationary Storage Containers, Delivery Vessels, and Bulk Plants) 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
6/21/2024	NOV	5033194	White Cap Construction Supply		17621 Scofield Ave, Shafter	Failure to register an engine greater than 50 HP.	93116 (ATCM for portable compression ignition engines)
6/25/2024	NOV	55296	Minter Field Airport District	S-1736	Minter Field, Shafter	Failure to maintain vapor recovery system. (Tom whip and curb hose).	2070 (Standards for Granting Applications) 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)