



Shafter Community Enforcement Update

Third Quarter 2024

Covering enforcement activities in the community from 7/1/2024 through 9/30/2024:

Residential Wood Burning – District Rule 4901

- District requirements in effect from Nov. 1 – Feb. 28/29 each year
- CERP commitment: Enhanced enforcement (four hours of enforcement on each wood burning curtailment day)
- No public complaints received
- No violation notices issued

Illegal Open Burning – District Rule 4103

- CERP commitment: One targeted enforcement effort every quarter
- 2 public complaints received
- No violation notices issued

Statewide Anti-Idling Enforcement

- CERP commitment: One targeted enforcement effort every quarter
- No violations of CARB's truck and bus regulation observed

Stationary Source Inspections

- CERP commitment: Increased inspection frequency at facilities with emission violations in the last 3 years
- 36 total stationary source inspections (29 compliance inspections, 3 follow-up inspections, 4 source test observation)

Enforcement Action Summary

- Stationary Source: 6 violation notices issued (3 emissions related, 3 procedural/administrative)
- Non-stationary Source: 1 violation notice issued (emissions related)

Public Complaints

- 5 total public complaints responded to in the community
 - 2 residential open burn
 - 3 fugitive dust
- 1 violation notice issued
- Complaints can be reported to the District by:
 - Telephone: (800) 870-1037
 - District website: www.valleyair.org
 - Through the District mobile app (Valley Air app)

Learn more: community.valleyair.org

Summary of Violations Found

Date	Type	Violation #	Issued To	Facility ID	Location	Description	Rules
8/6/2024	NOV	55604	Oil Well Service Company	S-9139	10255 Enos Ln, Shafter	Failure to maintain vapor recovery system. Torn upper hose.	2070 (Standards for Granting Applications), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
8/6/2024	NOV	5033362	Minter Field Airport District	S-1736	201 Aviation Street, Shafter	Failure to conduct and pass required vapor recovery tests (2nd Notice).	4621 (Gasoline Transfer into Stationary Storage Containers, Delivery Vessels, and Bulk Plants), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
8/7/2024	NOV	5033368	Rexco Development	S-10298	5408 Express Ave, Shafter	Failure to obtain a finalized Authority to Construct (ATC) prior to installing a fire pump engine >50 HP.	2010 (Permits Required), 4702 (Internal Combustion Engines - Phase 2)
8/7/2024	NOV	5033376	Pilot Travel Centers LLC	S-2012	17047 Zachary Ave, Bakersfield	Failure to conduct and pass required vapor recovery source tests (Dispenser Integrity, ISD Flow Meter, and V/L tests on Dispenser 9/10).	2070 (Standards for Granting Applications), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
9/12/2024	NOV	55609	Ahdi Enterprises Corp Dba Shafter Shell	S-2183	770 E Lerdo Hwy, Shafter	Failure to maintain vapor recovery system, torn hose on dispenser #2	2070 (Standards for Granting Applications), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
9/12/2024	NOV	55610	Jiffy's Store	S-239	538 Central Ave, Shafter	Failure to maintain vapor recovery system, Torn hose on dispenser #4.	2070 (Standards for Granting Applications), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
9/23/2024	NOV	5033608	John Balfanz Homes		SE Corner of E Ash Avenue & S Mannel Ave, Shafter	Failure to remove trackout as required by Rule 8041 Section 5.8.2 and DCP 2021-2557-S	8011 (General Requirements), 8041 (Carryout and Trackout)