



Stockton Enforcement Update

First Quarter 2024

Covering enforcement activities in the community from 1/1/24 through 3/31/24:

Fugitive Dust – District Regulation VIII

- CERP Commitment: One targeted enforcement effort during the 2nd and 3rd quarters, which tend to be the driest times of the year and most likely to have issues with fugitive dust from earthmoving activities
- No fugitive dust complaints received

Statewide Anti-Idling Enforcement

- CERP Commitment: One targeted enforcement effort during each quarter
- No public complaints of idling diesel trucks received
- 1 violation of CARB's anti-idling regulation observed during District enforcement

Stationary Source Inspections

- CERP commitment: Increased inspection frequency at facilities which receive an emissions violation
- 44 total stationary source inspections
(37 compliance inspections; 3 follow-up inspections & 4 source test observations)

Enforcement Action Summary

- Stationary Source: 8 violation notices issued (5 procedural/administrative, 3 emissions related)
- Non-stationary source: 3 violation notices issued

Public Complaints

- 5 public complaints responded to in the community
(3 open burn, 1 odor, 1 other)
- Complaints can be reported to the District by:
 - Telephone: (800) 870-1037
 - The District website: www.valleyair.org
 - Through the District mobile app (Valley Air app)

Learn more: community.valleyair.org

| Date | Type | Violation # | Issued To | Facility ID | Location | City | Description | Rules |
|-----------|------|-------------|-------------------------------------|-------------|-----------------------|----------|---|--|
| 1/16/2024 | NOV | 5032417 | Brian & Laura Peacock | | 920 W Vine St | Stockton | Use of a wood burning fireplace, wood burning heater, or outdoor wood burning device on an episodic wood burning curtailment day. | 4901 (Wood Burning Fireplaces and Wood Burning Heaters) |
| 1/16/2024 | NOV | 5032435 | Dte Stockton, Llc | N-645 | 2526 W Washington St | Stockton | Failure to demonstrate compliance with the ammonia slip emission rate limit at the 5/10/2023-5/11/2023 source test. | 2070 (Standards for Granting Applications) 4102 (Nuisance) 1081 (Source Sampling) |
| 2/7/2024 | NOV | 5032612 | Bwc Terminals Llc | N-10054 | Po Box 6218 | Stockton | Failure to source test within +/- 30 days source test anniversary date 12/6/XX. | 2070 (Standards for Granting Applications) 4305 (Boilers, Steam Generators, and Process Heaters-Phase 2) 4306 (Boilers, Steam Generators, and Process Heaters-Phase 3) 1081 (Source Sampling) |
| 2/26/2024 | NOV | 5032693 | Bwc Terminals Llc | N-10055 | Po Box 6218 | Stockton | Failure to source test within +/- 60 days of start up 03/20/23. | 2070 (Standards for Granting Applications) 4305 (Boilers, Steam Generators, and Process Heaters-Phase 2) 4306 (Boilers, Steam Generators, and Process Heaters-Phase 3) |
| 2/28/2024 | NOV | 5032715 | Diamond Foods, LLC | | 1050 S. Diamond St | Stockton | Failure to submit annual fee payment for 2021 to the Refrigerant Registration and Reporting System (R3). | 95384 (CA Code of Regulations, Title 17) |
| 2/29/2024 | NTC | 21472 | Acevedo & Son Auto Body And Paint | N-10045 | 366 W Lafayette St | Stockton | Failure to accurately record PM10 emissions | 2201 (New and Modified Stationary Source Review Rule) |
| 3/12/2024 | NOV | 5032772 | Nustar Terminals Ops Partnership Lp | N-829 | 2941 Navy Dr | Stockton | Organic liquid throughput exceed the 24,192,000 gallons in any one calendar year limit. | 2070 (Standards for Granting Applications) 2201 (New and Modified Stationary Source Review Rule) 2250 (Permit Exempt Equipment Registration) |
| 3/21/2024 | NOV | 49872 | Meza Trucking LLC | | 222-322 S. Fresno Ave | Stockton | Idling diesel >5 minutes within 100 feet of school. No immediate shut off, no ARB clean air certified sticker. | 2485 (CA Code of Regulations, Title 17) 2070 (Standards for Granting Applications) |
| 3/26/2024 | NOV | 5032845 | Arrow Infrastructure Holding Ia Llc | N-2369 | 2700 W Washington St | Stockton | Vapor leak exceeding 10,000 ppm measured as methane discovered on lane #3's front arm vapor hose for gasoline while in operation. | 2520 (Federally Mandated Operating Permits) 4624 (Transfer of Organic Liquids) |
| 3/29/2024 | NTC | 5031910 | Synergy | N-103 | 3440 E Main St | Stockton | Operating without a valid Permit to Operate, failure to submit a Transfer of Ownership application. | 2010 (Permits Required) |
| 3/29/2024 | NTC | 5031911 | Synergy | N-175 | 642 N. Hunter St | Stockton | Operating without a valid Permit to Operate, failure to submit a Transfer of Ownership application. | 2010 (Permits Required) |