



## **Stockton Enforcement Update**

Third Quarter 2023

Covering enforcement activities in the community from 7/1/23 through 9/30/23:

### **Fugitive Dust – District Regulation VIII**

- CERP Commitment: One targeted enforcement effort during the 2<sup>nd</sup> and 3<sup>rd</sup> quarters, which tend to be the driest times of the year and most likely to have issues with fugitive dust from earthmoving activities
- 8 construction project sites inspected for compliance with District and state regulations
- 1 fugitive dust complaint responded to

### **Statewide Anti-Idling Enforcement**

- CERP Commitment: One targeted enforcement effort during each quarter
- No public complaints of idling diesel trucks received
- No violations of CARB's anti-idling regulation observed during District enforcement

### **Stationary Source Inspections**

- CERP commitment: Increased inspection frequency at facilities which receive an emissions violation
- 49 total stationary source inspections  
(46 compliance inspections & 3 source test observations)

### **Enforcement Action Summary**

- Stationary Source: 18 violation notices issued (11 procedural/administrative, 7 emissions related)
- Non-stationary Source: No violation notices issued

### **Public Complaints**

- 5 public complaints responded to in the community  
(1 open burn, 1 visible emission, 1 fugitive dust, 1 odor, 1 other)
- Complaints can be reported to the District by:
  - Telephone: (800) 870-1037
  - The District website: [www.valleyair.org](http://www.valleyair.org)
  - Through the District mobile app (Valley Air app)

**Learn more: [community.valleyair.org](http://community.valleyair.org)**

Date	Type	Violation #	Issued To	Facility ID	Location	City	Description	Rules
7/5/2023	NOV	5031292	Abdo Thabit Nashir	N-8540	713 N El Dorado St	Stockton	Failure to conduct and pass the required vapor recovery performance testing.	2070 (Standards for Granting Applications) 4621 (Gasoline Transfer into Stationary Storage Containers, Delivery Vessels, and Bulk Plants)
7/5/2023	NOV	5031294	Juva Stockton, Inc	N-9767	633 San Juan Avenue	Stockton	Engine #5 emitted NOx and CO above the permitted limits.	4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks) 2070 (Standards for Granting Applications)
7/5/2023	NOV	5031297	State of CA 2nd Dist. Ag Association	N-788	1658 S Airport Way	Stockton	Failure to conduct and pass the required vapor performance testing.	2070 (Standards for Granting Applications) 4621 (Gasoline Transfer into Stationary Storage Containers, Delivery Vessels, and Bulk Plants)
7/6/2023	NOV	53662	Mobil Stockton #1/Abdo Nashir	N-175	642 N Hunter St	Stockton	Failed to maintain the vapor recovery system. Tank #2 87-grade must be OPW series 1711.	4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks) 2070 (Standards for Granting Applications)
7/6/2023	NOV	5031305	Tesoro Logistics Operations Llc	N-845	3003 Navy Dr	Stockton	The metallic shoe-type seal was not installed with a minimum vertical distance of 18 inches above the stored liquid surface.	4621 (Gasoline Transfer into Stationary Storage Containers, Delivery Vessels, and Bulk Plants) 2520 (Federally Mandated Operating Permits)
7/7/2023	NOV	5031306	Verizon Wireless - Stockton Msc	N-4560	3202 Mourfield Ave	Stockton	Failure to acquire required permits	4623 (Storage of Organic Liquids) 2010 (Permits Required) 2020 (Exemptions) 2280 (Portable Equipment Registration)
7/7/2023	NOV	53663	SRH Food & Gas Market	N-258	749 E Martin Luther King Jr Blvd	Stockton	Failure to conduct and pass the required vapor recovery performance testing.	2070 (Standards for Granting Applications) 4621 (Gasoline Transfer into Stationary Storage Containers, Delivery Vessels, and Bulk Plants)
7/11/2023	NOV	5031326	Nustar Terminals Ops Partnership Lp	N-829	2941 Navy Dr	Stockton	Failure to operate truck loading racks such that there are no leaks, three vapor leaks above 10,000 ppm discovered.	4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks) 2010 (Permits Required) 2520 (Federally Mandated Operating Permits)
7/12/2023	NOV	49070	Ac Painting	N-8925	620 San Juan Ave	Stockton	1) Failure to properly maintain daily records for coatings usage, VOC's, and PM10's as is required by the Permit to Operate. 2) Failure to submit the 2022 Emissions Inventory by the due date of 5/25/2023.	4642 (Transfer of Organic Liquids) 1160 (Emission Statements) 2070 (Standards for Granting Applications) 2201 (New and Modified Stationary Source Review Rule) 4606 (Wood Products Coating Operations)
7/12/2023	NOV	5031336	Juva Stockton, Inc	N-9767	633 San Juan Ave	Stockton	1. Source test results indicate that the CO emissions exceeded the permitted limit of 20 ppm @ 15% O2 and 0.17 g/bhp-hr. 2. Source test results were submitted to the District more than 60 days after the test on 3/7/23 was conducted. 3. Facility failed to source test the engine within +/-30 days of the anniversary date of 1/14/23.	2070 (Standards for Granting Applications) 2201 (New and Modified Stationary Source Review Rule)
7/17/2023	NTC	5031352	East Bay Municipal Utility District	N-997	1804 W Main St	Stockton	Operating a gasoline dispensing facility without certified components- failure to install two Enhanced Conventional (ECO Nozzle) gasoline dispensing nozzles per Executive Order (EO) NVR-1.	2070 (Standards for Granting Applications) 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
8/4/2023	NOV	5031433	Stockton Rwcf	N-811	2500 Navy Dr	Stockton	1) Failure to change the motor oil and the oil filter at least every 500 hours of operation or annually, whichever comes first. 2) Failure to provide a deviation report within 10 days.	2070 (Standards for Granting Applications) 2520 (Federally Mandated Operating Permits)
8/22/2023	NTC	5031312	San Joaquin County - Public Works	P-7094	1810 E Hazelton Ave	STOCKTON	Failure to submit quarterly operational use records according to your Registered Portable Equipment to the District within 30 days after the end of each calendar quarter for the following quarters: 2019: Q,2Q4; 2020: Q3,Q4; 2021: Q,Q2,Q3,Q4; 2022: Q1,Q3,Q4.	2280 (Portable Equipment Registration) 2070 (Standards for Granting Applications)
9/6/2023	NOV	53666	Vanco Truck & Auto Plaza	N-921	1033 W Charter Wy	Stockton	Failure to properly respond to ISD alarms and to properly maintain an ISD alarm log.	4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
9/12/2023	NTC	5031421	Ramirez Auto Body & Repair	N-8932	1025 E Hazelton Ave	Stockton	Failure to pay annual Air Toxic Fees	3110 (Air Toxic Fees)
9/19/2023	NOV	5031601	Arrow Infrastructure Holding Ia Llc	N-2369	2700 W Washington St	Stockton	Failure to accurately report information on the Annual Compliance Certification (ACC) for reporting period 01/01/2022 to 12/31/2022.	2070 (Standards for Granting Applications) 2520 (Federally Mandated Operating Permits)
9/21/2023	NOV	5031618	Stockton RWCF	N-811	2500 Navy Dr	Stockton	Failure to maintain the fuel sulfur content at or below 5 grains of total sulfur per 100 standard cubic feet.	2070 (Standards for Granting Applications) 2520 (Federally Mandated Operating Permits)
9/27/2023	NOV	53669	California Stop	N-2500	2224 S Manthey Rd	Stockton	Failure to maintain the Phase II vapor recovery equipment. (FP#6 loose spout; FP#8 torn whip hose).	4702 (Internal Combustion Engines - Phase 2) 2070 (Standards for Granting Applications) 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)