

Shafter Community Enforcement Update Fourth Quarter 2023

Covering enforcement activities in the community from 10/1/2023 through 12/31/2023:

Residential Wood Burning – District Rule 4901

- District requirements in effect from Nov. 1 Feb. 28/29 each year
- CERP commitment: Enhanced enforcement (four hours of enforcement on each wood burning curtailment day)
- No public complaints received

Illegal Open Burning – District Rule 4103

- CERP commitment: One targeted enforcement effort every quarter
- 5 public complaints received

Statewide Anti-Idling Enforcement

- CERP commitment: One targeted enforcement effort every quarter
- No violations of CARB's truck and bus regulation observed

Stationary Source Inspections

- CERP commitment: Increased inspection frequency at facilities with emission violations in the last 3 years
- 36 total stationary source inspections (29 compliance inspections, 5 follow-up inspections, 1 breakdown investigation, 1 source test observation)

Enforcement Action Summary

- Stationary Source: 10 violation notices issued (8 emissions related, 2 procedural/administrative)
- Non-stationary Source: 6 violation notices issued

Public Complaints

- 5 total public complaints responded to in the community (5 open burn)
- Complaints can be reported to the District by:
 - Telephone: (800) 870-1037
 - District website: <u>www.valleyair.org</u>
 - Through the District mobile app (Valley Air app)

Learn more: community.valleyair.org

Summary of Violations Found

Date	Туре	Violation #	Issued To	Facility ID	Location	Description	Rules
10/09/2023	NOV	5031680	Bidart Bros		7th Standard Road & Zerker Road, Shafter	Operating without a Conservation Management Practices Plan.	4550 (Conservation Management Practices)
10/27/2023	NOV	5031775	Pilot Travel Centers LLC	S-2012	17047 Zachary Ave, Bakersfield	Operating a gasoline vapor recovery system with a non-certified component. (Curb hose #10 not certified)	2070 (Standards for Granting Applications) 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
10/30/2023	NOV	5031781	Amelia Gomez		29773 Riverside Street, Shafter	Open burn of prohibited materials.	4103 (Open Burning)
10/31/2023	NOV	5031702	Skyview Dairy Shafter	S-6706	28989 Riverside St, Shafter	Modifying an emission unit without an ATC modification.	2010 (Permits Required)
11/07/2023	NOV	5031779	Plains Lpg Services Lp	S-71	7Th Standard Rd & Beech Ave, Shafter	Discovery of 9 leaks greater than 1000 ppm	2520 (Federally Mandated Operating Permits)2070 (Standards for Granting Applications) 4624 (Transfer of Organic Liquids)
11/13/2023	NOV	5031682	Patrick Tritz		5408 Express Avenue, Shafter	Failure to submit an Air Impact Assessment (AIA) application no later than applying for final discretiona approval as required by Rule 9510, Sect. 5.0. Second Violation	ry 9510 (Indirect Source Review (ISR))
11/21/2023	NOV	47742	Ana Sanchez		18862 Beech Ave, Shafter	Illegal Open Burning	4103 (Open Burning)
11/30/2023	NOV	5031995	Elk Corp Of Texas	S-2033	6200 Zerker Rd, Shafter	Failure to install fuel meters	4320 (Advance Emission Reduction Options for Bollers, Steam Generators, and Process Heaters) 2520 (Federally Mandated Operating Permits) 2070 (Standards for Granting Applications)
12/05/2023	NOV	5032042	J.P. Oil Company, Llc	S-2865	Light Oil Central, Shafter	Discovery of a leak greater than 50,000 PPM	4409 (Components at Light Crude Oil Production Facilities, Natural Gas Production Facilities, and Natural Gas Processing Facilities)
12/11/2023	NOV	5032082	J.P. Oil Company, Llc	S-2865	Light Oil Central, Shafter	Unit exceeded permitted CO limits during annual source test.	4702 (Internal Combustion Engines - Phase 2) 2201 (New and Modified Stationary Source Review Rule)
12/13/2023	NOV	5032108	Amazon.Com Services LLC - BFL2	S-9794	4500 Express Ave, Shafter	Engine exceeded calendar limit of 50hrs/yr for 2023	4702 (Internal Combustion Engines - Phase 2) 2070 (Standards for Granting Applications)
12/18/2023	NOV	5032125	Alliance Ready Mix, Inc.	S-9156	100 Carver St, Shafter	Operating a CARB PERP Engine to supplement a stationary source.	4702 (Internal Combustion Engines - Phase 2) 2010 (Permits Required)
12/18/2023	NOV	5032149	Alliance Ready Mix, Inc.	S-9156	100 Carver St, Shafter	Operating batch mixing process without functional magnahelic differential pressure gauge. Not maintaining adequate maintenance procedures resulting in emission of air contaminants into the atmosphere.	2201 (New and Modified Stationary Source Review Rule) 2070 (Standards for Granting Applications)
12/27/2023	NOV	5032295	J.P. Oil Company, LLC	S-2865	Light Oil Central, Shafter	Permittee failed to submit a source test results report to the District within 60 days of field testing.	2070 (Standards for Granting Applications) 1081 (Source Testing)
12/27/2023	NOV	5032303	Mario Carranza		302 Karla Street, Shafter	Illegal Open Burn	4103 (Open Burning)
12/28/2023	NOV	47743	Martin Quihuiz		30392 Orange St, Shafter	Illegal Burning	93113 (CA Code of Regulations, Title 17)