



Arvin-Lamont Community Enforcement Update **Third Quarter 2024**

Covering enforcement activities in the community from 7/1/2024 through 9/30/2024:

Fugitive Dust – District Regulation VIII

- CERP commitment: One targeted enforcement effort during the 2nd (April – June) and 3rd (July – September) quarters, which tend to be the driest times of the year and most likely to have issues with fugitive dust from earthmoving activities
- 2 public complaints received
- 1 violation of Regulation VIII observed

Statewide Anti-Idling Enforcement

- CERP commitment: One targeted enforcement effort every quarter
- No violations of CARB's truck and bus regulation observed

Stationary Source Inspections

- CERP commitment: Increased inspection frequency at facilities with emission violations in the last 3 years
- 38 total stationary source inspections (28 compliance inspections, 6 follow-up inspections, 3 breakdown/deviation investigation, 1 source test observation)

Enforcement Action Summary

- Stationary Source: 19 violation notices issued (2 procedural/administrative, 17 emissions related); 4 notices to comply issued (procedural/administrative)
- Non-stationary Source: 3 violation notices issued (emissions related)

Public Complaints

- 8 total public complaints responded to in the community
 - 1 agricultural burn
 - 2 fugitive dust
 - 5 residential open burns
- 1 violation notice issued
- Complaints can be reported to the District by:
 - Telephone: (800) 870-1037
 - District website: www.valleyair.org
 - Through the District mobile app (Valley Air app)

Learn more: community.valleyair.org

Summary of Violations Found

Date	Type	Violation #	Issued To	Facility ID	Location	Description	Rules
7/3/2024	NOV	5033227	The Termo Co	S-1137	Brite/Jewett and Mt. View Leases,	I. Discovery of one greater than 50,000 PPM leak on gauge valve on Well Brite #88-16; II. Discovery of a greater than 50,000 PPM leak on Tank Brite 2 on the hatch.	95669 (CA Code of Regulations, Title 17)
7/17/2024	NOV	5033278	S & S Mini Mart, Inc	S-679	10618 Main St, Lamont	Failure to conduct and pass the required vapor recovery performance testing. (V/L not conducting on fueling point #6)	2070 (Standards for Granting Applications), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks) 2070 (Standards for Granting Applications)
7/24/2024	NOV	5033302	Kern Energy	S-37	Panama Ln & Weedpatch Hwy, Bakersfield	Failure to comply with H2S limit of 162 ppmv (06/17/24, 06/18/24, 06/19/24)	2520 (Federally Mandated Operating Permits) 2070 (Standards for Granting Applications), 2201 (New and Modified Stationary Source Review Rule), 2520 (Federally Mandated Operating Permits), 4623 (Storage of Organic Liquids)
7/24/2024	NOV	5033304	Kern Energy	S-37	Panama Ln & Weedpatch Hwy, Bakersfield	Failure to maintain vapor recovery system in operation	2070 (Standards for Granting Applications), 2201 (New and Modified Stationary Source Review Rule), 2520 (Federally Mandated Operating Permits), 4623 (Storage of Organic Liquids)
8/1/2024	NOV	5033343	Kern Energy	S-37	7724 E Panama Ln, Bakersfield	Failure to comply with H2S limit of 162 ppmv; Failure to submit Deviation Report within 10-days of discovery date.	2070 (Standards for Granting Applications), 2520 (Federally Mandated Operating Permits)
8/2/2024	NOV	5033296	Charter Communications	S-8167	10311 Stobaugh Street, Lamont	Facility is located within 500 feet of a school and has their weekly automated maintenance testing scheduled during non-permitted hours (between 7:30am-8:00am).	2070 (Standards for Granting Applications), 93115 (ATCM for Stationary Compression Ignition Engines)
8/2/2024	NOV	5033346	ETCHISON FARMS		SW OF DIGORGIO RD. AND SOUTH FAIRFAX RD., BAKERSFIELD	Open burning of prohibited material	4103 (Open Burning)
8/16/2024	NTC	5032071	H & S Chevron Food Mart Inc	S-238	300 Bear Mountain Blvd, Arvin	Failure to conduct and pass the required vapor recovery performance testing (Hirt Burn Operability test).	4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks), 43960 (CA Health & Safety Code 41960) 2070 (Standards for Granting Applications)
8/19/2024	NOV	5033427	Dillon & Sons dba The Barn #4	S-6820	11336 Comanche Dr, Arvin	Failure to maintain the vapor recovery system. (Whip hose #4 torn, curb hose #8 torn.)	4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks) 2070 (Standards for Granting Applications), 2520 (Federally Mandated Operating Permits), 4455 (Components at Petroleum Refineries, Gas Liquids Processing Facilities, and Chemical Plants)
8/20/2024	NOV	5033434	Kern Energy	S-37	Panama Ln & Weedpatch Hwy, Bakersfield	Exceedance of allowable leaks in Table 2 per Rule 4455: Valves; Threaded Connections; and Other components.	2520 (Federally Mandated Operating Permits), 4455 (Components at Petroleum Refineries, Gas Liquids Processing Facilities, and Chemical Plants)
8/20/2024	NTC	5032074	Anthony Vineyards Inc	S-7832	425 King St, Arvin	Failure to submit the 2023 Emissions Inventory Report to the San Joaquin Valley APCD by May 1st, 2024.	93403 (CA Code of Regulations, Title 17)
8/21/2024	NTC	5032077	Grege Petroleum Service	S-2257	901 S Derby, Arvin	Failure to conduct and pass the required vapor recovery performance testing. (Phase I EVR Static Leak Decay)	2070 (Standards for Granting Applications), 4621 (Gasoline Transfer into Stationary Storage Containers, Delivery Vessels, and Bulk Plants), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
8/26/2024	NOV	5033466	One Stop Lamont	S-9091	12816 Main St, Lamont	Failure to maintain the vapor recovery system. (Curb hose torn on fueling point #3.)	2070 (Standards for Granting Applications), 4622 (Gasoline Transfer into Motor Vehicle Fuel Tanks)
8/28/2024	NOV	5033305	Kern Energy	S-37	Panama Ln & Weedpatch Hwy, Bakersfield	Failure to comply with H2S limit of 100ppm: -1, -3, -4, -116 on 7-24-24 -77, -118, -119, -122 on 7-18-24, 7-24-24, and 7-26-24 and Failure to comply with H2S limit of 162ppm: -38 on 7-24-24	2070 (Standards for Granting Applications), 2201 (New and Modified Stationary Source Review Rule), 2520 (Federally Mandated Operating Permits), 4301 (Fuel Burning Equipment)
8/29/2024	NOV	5033489	Windsor Arvin Healthcare Llc	S-7013	323 Campus Dr, Arvin	Operating on a suspended permit.	2010 (Permits Required)
9/3/2024	NOV	5033515	Kern Energy	S-37	Panama Ln & Weedpatch Hwy, Bakersfield	Failure to comply with H2S limit of 162 ppmv (08/07/24, 08/08/24)	2070 (Standards for Granting Applications), 2520 (Federally Mandated Operating Permits)
9/3/2024	NOV	5033493	Kern Energy	S-37	Panama Ln & Weedpatch Hwy, Bakersfield	Failure to comply with H2S limit of 100ppm	2070 (Standards for Granting Applications), 2201 (New and Modified Stationary Source Review Rule), 2520 (Federally Mandated Operating Permits), 4301 (Fuel Burning Equipment)
9/4/2024	NTC	5032106	GOGO LLC	S-7235	15311 Cuda Rd, Arvin	Failure to submit 2023 emission inventory by May 1, 2024 deadline.	93403 (CA Code of Regulations, Title 17)
9/13/2024	NOV	5033565	Dillon & Sons dba The Barn #4	S-6820	11336 Comanche Dr, Arvin	Failure to maintain the vapor recovery system. (87-grade vapor adaptor frozen.)	2070 (Standards for Granting Applications), 4621 (Gasoline Transfer into Stationary Storage Containers, Delivery Vessels, and Bulk Plants)
9/14/2024	NOV	5033681	Rigoberto Chavez		8901 Fuller Dr., BAKERSFIELD	Open burning of yard waste as prohibited by District Rule 4103	4103 (Open Burning)
9/16/2024	NOV	5033586	City of Arvin - Public Works		5th Ave & A St, Arvin	Failure to immediately clean up trackout greater than 50 feet as required in Rule 8041.	8041 (Carryout and Trackout)
9/17/2024	NOV	5033594	Kern Energy	S-37	Panama Ln & Weedpatch Hwy, Bakersfield	Exceedance of annual average heat input	2201 (New and Modified Stationary Source Review Rule), 2520 (Federally Mandated Operating Permits)
9/17/2024	NOV	5033597	Kern Energy	S-37	Panama Ln & Weedpatch Hwy, Bakersfield	Exceedance of True Vapor Pressure (TVP) limit of liquids transferred	2201 (New and Modified Stationary Source Review Rule), 2520 (Federally Mandated Operating Permits)
9/17/2024	NOV	5033598	Grege Petroleum Service	S-1647	868 S Derby, Arvin	Failure to maintain the vapor recovery system. Offloading vapor hose found torn and leaking in excess of 10,000 ppm.	2070 (Standards for Granting Applications), 4621 (Gasoline Transfer into Stationary Storage Containers, Delivery Vessels, and Bulk Plants)
9/17/2024	NOV	5033599	Kern Energy	S-37	Panama Ln & Weedpatch Hwy, Bakersfield	Exceedance of H2S limits	2070 (Standards for Granting Applications), 2201 (New and Modified Stationary Source Review Rule), 2520 (Federally Mandated Operating Permits)
9/24/2024	NOV	5033616	Kern Energy	S-4162	7724 E. Panama Lane, Bakersfield	Failure to comply with VOC control efficiency rate of 99.5% in the months of January, April, May and August 2023.	2070 (Standards for Granting Applications), 2201 (New and Modified Stationary Source Review Rule)